

July 9, 2026

Mr. William Butler
Williamson County Schools
1761 West Main Street
Franklin, Tennessee

**Re: Summary Report of 2026 Drinking Water Sampling and Analysis
Williamson County Schools**

Dear Mr. Butler:

EnSafe Inc. is pleased to provide this summary report for the recently completed drinking water sampling and analysis activities performed at Williamson County Schools (WCS) for the 2026 school calendar year. The objective of the activities was to help ensure WCS's compliance with the law, Tennessee Code Annotated (TCA) §49-2-133.

SCOPE OF WORK

The sampling and analysis activities for the 2026 school calendar year were performed in general accordance with the WCS Lead in Drinking Water Program, dated June 17, 2019. The testing focused on representative drinking water supply locations to provide an overview of drinking water quality in 25 schools constructed prior to January 1, 1998. The sampling was completed June 2 through 18, 2026. WCS coordinated with EnSafe regarding the selection of the schools, scheduling, and access. Water samples were collected from fixtures (sampling locations) strategically selected to help ensure representative first-draw water samples. Quality assurance (QA) samples were also collected from the schools, including duplicate first draw samples and field blank samples. Each sample was collected in a laboratory-provided container, labeled with the proper school name and sample identification. A total of 541 samples from the June 2026 activities were transported to Waypoint Analytical Laboratories under chain-of-custody control for analysis of lead concentrations using the United States Environmental Protection Agency (EPA) Method 200.8.

Upon receipt of the laboratory analytical results, the results were reviewed and compared to the action levels of 15 and 20 parts per billion (ppb) referenced in T.C.A. § 49-2-133. Notifications of the results relative to the action levels were then provided to WCS. Additionally, the results were entered into a database and into a detailed table previously requested by WCS. As discussed in the following section, the results were favorable.

FINDINGS

The collection of 541 samples was performed from June 2 through 18, 2026. Laboratory results, sampling locations, and fixture types are included in Attachment A of this report. The laboratory results indicated that no lead concentrations exceeded the action levels of 15 ppb or 20 ppb in the first-draw samples. As such, no additional sampling of individual taps was required. Additionally, because of the low concentrations, no exceedance notifications were required to be submitted to parents, guardians, or governmental agencies.

Thank you again for your time and consideration regarding this project. If you have any questions or require additional information, please contact us at 615-255-9300.

Sincerely,

EnSafe Inc.


By: Rachel Shepherd
Environmental Scientist


Ronald T. Dow, P.G.
Senior Project Manager

Attachments:

Attachment A — Laboratory Results Summary

Attachment A
Laboratory Results Summary

WILLIAMSON COUNTY SCHOOLS 2026 DRINKING WATER RESULTS SUMMARY				
School Name	Sampled Date/Time	Sample ID	Result	Location Notes
Bethesda ES	6/18/2026 6:17	FB-01	<0.500	Quality Control Field Blank
Bethesda ES	6/18/2026 6:29	WC-47-FD	<0.500	Left WC with bottle filler outside gym with bottle filler
Bethesda ES	6/18/2026 6:30	WC-48-FD	1.49	Right wc outside gym
Bethesda ES	6/18/2026 6:32	WC-31-FD	<0.500	Next to Room 616 (office/admin) door, with bottle filler
Bethesda ES	6/18/2026 6:35	WC-20-FD	<0.500	Next to mechanical room
Bethesda ES	6/18/2026 6:36	WC-21-FD	<0.500	Between Room 202 & boys bathroom, left WC with bottle filler
Bethesda ES	6/18/2026 6:37	WC-22-FD	<0.500	Between Room 202 & Boys bathroom, right WC
Bethesda ES	6/18/2026 6:40	WC-34-FD	0.518	Left WC, next to Room 201 & boy's restroom
Bethesda ES	6/18/2026 6:41	WC-44-FD	<0.500	Right fountain in hallway next to 102 with bottle filler
Bethesda ES	6/18/2026 6:46	WC-04-FD	<0.500	Across from Room 702A, bubbler without bottle filler
Bethesda ES	6/18/2026 6:47	WC-40-FD	<0.500	Right fountain in hallway across from cafeteria
Bethesda ES	6/18/2026 6:48	WC-39-FD	<0.500	WC on left across from cafeteria
Bethesda ES	6/18/2026 6:51	KT-41-FD	<0.500	Kitchen tap on the left, furthest from the door, 3 bay sink
Bethesda ES	6/18/2026 6:51	KT-41-FD-D	<0.500	Kitchen tap on the left, furthest from the door, 3 bay sink
Brentwood HS	6/4/2026 6:05	FB-01-FD	<0.500	Quality Control Field Blank
Brentwood HS	6/4/2026 6:24	WC-38-FD	<0.500	In cafeteria, did not sample from bottle filler
Brentwood HS	6/4/2026 6:24	WC-38-FD-D	<0.500	In cafeteria, did not sample from bottle filler
Brentwood HS	6/4/2026 6:31	KT-03-FD	2.11	Kitchen prep sink tap
Brentwood HS	6/4/2026 6:37	WC-04-FD	<0.500	Across from Room 702A, bubbler without bottle filler (bubbler on the right)
Brentwood HS	6/4/2026 6:38	WC-05-FD	<0.500	Right WC outside locker rooms
Brentwood HS	6/4/2026 6:48	WC-10-FD	<0.500	WC near gym
Brentwood HS	6/4/2026 6:54	WC-11-FD	<0.500	Right WC in campbell center
Brentwood HS	6/4/2026 6:55	WC-12-FD	<0.500	Left WC in campbell center
Brentwood HS	6/4/2026 7:02	WC-20-FD	<0.500	Next to mechanical room
Brentwood HS	6/4/2026 7:05	WC-23-FD	<0.500	WC next to C4 & C5 rooms, left (taller) WC
Brentwood HS	6/4/2026 7:08	WC-26-FD	<0.500	WC next to room C2, in front of library, bottle filler
Brentwood HS	6/4/2026 7:17	WC-40-FD	<0.500	Next to classroom F1A, taller fountain
Brentwood HS	6/4/2026 7:18	WC-41-FD	<0.500	Shorter, next to F1A; WC in front of Room 620, left WC
Brentwood HS	6/4/2026 7:23	WC-42-FD	<0.500	WC in front of Room B18
Brentwood HS	6/4/2026 7:24	WC-43-FD	<0.500	Left wc with bottle filler 700 hallway
Brentwood HS	6/4/2026 7:27	WC-08-FD	<0.500	Taller
Brentwood HS	6/4/2026 7:28	WC-09-FD	<0.500	Short
Brentwood HS	6/4/2026 7:31	WC-27-FD	0.615	WC in front of Room A1, (taller) left WC
Brentwood HS	6/4/2026 7:32	WC-28-FD	2.26	WC in front of Room A1, (shorter) right WC
Brentwood HS	6/4/2026 7:34	WC-30-FD	<0.500	WC in front of Room A4, (shorter) right WC
Brentwood HS	6/4/2026 7:36	WC-29-FD	<0.500	WC in front of Room A4, taller, left WC. Sampled from bubbler head, bottle filler not working
Brentwood HS	6/4/2026 7:40	WC-06-FD	<0.500	WC in front of Room A7, left (taller) WC
Brentwood HS	6/4/2026 7:41	WC-31-FD	<0.500	next to Room 616 (office/admin) door. Sample taken from bottle filler
Brentwood HS	6/4/2026 7:44	WC-34-FD	<0.500	Left WC, next to Room 201 & boy's restroom
Brentwood HS	6/4/2026 7:45	WC-35-FD	<0.500	WC in front of Room A19, right (shorter) WC
Brentwood HS	6/4/2026 7:49	WC-36-FD	<0.500	WC in front if Room A22, left (taller) WC.
Brentwood HS	6/4/2026 7:50	WC-37-FD	<0.500	WC in front of Room A22, right (shorter) WC
Brentwood HS	6/4/2026 7:56	WC-21-FD	<0.500	between Room 202 & boys bathroom, left WC & sampled from bottle filler
Centennial HS	6/16/2026 6:14	FB-01	<0.500	Quality Control Field Blank
Centennial HS	6/16/2026 6:20	WC-05-FD	<0.500	Upper left fountain in hall by room 115
Centennial HS	6/16/2026 6:26	WC-29-FD	<0.500	Fountain in teachers work area with bottle filler
Centennial HS	6/16/2026 6:27	TL-11-FD	<0.500	Teachers work area tap
Centennial HS	6/16/2026 6:29	TL-11-FD-D	<0.500	Library office next to library doors
Centennial HS	6/16/2026 6:31	WC-24-FD	<0.500	Taller left water fountain next to room 137 with bottle filler
Centennial HS	6/16/2026 6:32	WC-25-FD	<0.500	Shorter right water fountain in hallway next to room 137
Centennial HS	6/16/2026 6:35	WC-23-FD	<0.500	Lower left fountain in n hall by office
Centennial HS	6/16/2026 6:39	WC-22-FD	<0.500	Right taller fountain in hallway by office
Centennial HS	6/16/2026 6:42	WC-08-FD	<0.500	Taller right fountain in hallway by concessions near gym entry with bottle filler
Centennial HS	6/16/2026 6:45	WC-10-FD	<0.500	Lower left fountain by women's restroom near gym entry
Centennial HS	6/16/2026 6:46	WC-09-FD	<0.500	Taller right fountain by women's restroom near gym entry
Centennial HS	6/16/2026 6:50	WC-28-FD	<0.500	Boys locker room fountain
Centennial HS	6/16/2026 6:57	KT-06-FD	0.702	Kitchen tap next to kitchen office
Centennial HS	6/16/2026 7:10	WC-20-FD	<0.500	Upper left hallway fountain by room 252
Centennial HS	6/16/2026 7:11	WC-21-FD	<0.500	Lower right hallway fountain by room 252
Centennial HS	6/16/2026 7:12	WC-18-FD	<0.500	Upper left fountain in hallway next to room 239 with bottle filler
Centennial HS	6/16/2026 7:13	WC-19-FD	<0.500	Lower right fountain in hallway next to room 239 with bottle filler
Centennial HS	6/16/2026 7:21	WC-13-FD	<0.500	Right (taller) cooler; adjacent to women's restroom near exit
Centennial HS	6/16/2026 7:22	WC-15-FD	<0.500	2nd floor, left wc in front of rm 224
Centennial HS	6/16/2026 7:36	WC-04-FD	<0.500	Across from Room 702A, bubbler without bottle filler (bubbler on the right)
Centennial HS	6/16/2026 7:37	WC-14-FD	<0.500	2nd floor, right wc in front of rm 224
College Grove ES	6/18/2026 7:14	FB-01	<0.500	Quality Control Field Blank
College Grove ES	6/18/2026 7:17	WC-02-FD	<0.500	In hallway before Room 202, (cooler on right)
College Grove ES	6/18/2026 7:29	SOW-40-FD	0.623	Room 204
College Grove ES	6/18/2026 7:30	SOW-41-FD	<0.500	Room 205
College Grove ES	6/18/2026 7:32	SOW-14-FD	0.886	Room 208
College Grove ES	6/18/2026 7:34	SOW-44-FD	<0.500	Room 212
College Grove ES	6/18/2026 7:37	SOW-45-FD	<0.500	Room 213
College Grove ES	6/18/2026 7:42	SOW-48-FD	1.15	Room 300
College Grove ES	6/18/2026 7:43	SOW-46-FD	3.13	Room 301

WILLIAMSON COUNTY SCHOOLS 2026 DRINKING WATER RESULTS SUMMARY				
School Name	Sampled Date/Time	Sample ID	Result	Location Notes
College Grove ES	6/18/2026 7:45	WC-18-FD	<0.500	Right wc in front of rm 301 with bottle filler
College Grove ES	6/18/2026 7:47	WC-23-FD	<0.500	Left fountain in front of room 301
College Grove ES	6/18/2026 7:49	SOW-20-FD	3.60	Room 304
College Grove ES	6/18/2026 7:50	SOW-47-FD	1.34	Room 303
College Grove ES	6/18/2026 7:51	SOW-03-FD	<0.500	Room 304
College Grove ES	6/18/2026 7:54	SOW-19-FD	1.62	Room 305
College Grove ES	6/18/2026 7:58	WC-21-FD	<0.500	between Room 202 & boys bathroom, left WC with bottle filler
College Grove ES	6/18/2026 8:00	SOW-49-FD	2.83	Room 404
College Grove ES	6/18/2026 8:03	SOW-24-FD	<0.500	Room 407
College Grove ES	6/18/2026 8:04	SOW-25-FD	<0.500	Room 408
College Grove ES	6/18/2026 8:06	SOW-26-FD	<0.500	Room 411
College Grove ES	6/18/2026 8:08	SOW-27-FD	<0.500	Room 412
College Grove ES	6/18/2026 8:09	SOW-04-FD	<0.500	Room 413
College Grove ES	6/18/2026 8:12	TL-09-FD	<0.500	Teacher's lounge sink
College Grove ES	6/18/2026 8:12	TL-09-FD-D	<0.500	Teacher's lounge sink
College Grove ES	6/18/2026 8:13	KT-05-FD	0.638	3-bay kitchen sink furthest right, closest to door
Crockett ES	6/4/2026 7:01	KT-03-FD	<0.500	Food preparation tap
Crockett ES	6/4/2026 7:01	KT-03-FD-D	<0.500	Food preparation tap
Crockett ES	6/4/2026 6:50	SOW-23-FD	<0.500	Room 1
Crockett ES	6/4/2026 6:54	SOW-24-FD	<0.500	Room 2
Crockett ES	6/4/2026 6:28	SOW-28-FD	<0.500	Room 107
Crockett ES	6/4/2026 6:26	SOW-29-FD	<0.500	Room 15
Crockett ES	6/4/2026 6:22	SOW-30-FD	<0.500	Room 16
Crockett ES	6/4/2026 6:24	SOW-31-FD	<0.500	Room 17
Crockett ES	6/4/2026 6:18	SOW-32-FD	<0.500	Room 305
Crockett ES	6/4/2026 6:20	SOW-33-FD	<0.500	Room 305
Crockett ES	6/4/2026 6:16	SOW-34-FD	<0.500	Room 205
Crockett ES	6/4/2026 6:15	SOW-35-FD	<0.500	Room 111, to the left
Crockett ES	6/4/2026 6:10	SOW-36-FD	<0.500	Room 203
Crockett ES	6/4/2026 6:14	SOW-37-FD	1.50	Room 204
Crockett ES	6/4/2026 6:52	SOW-41-FD	<0.500	Room 202
Crockett ES	6/4/2026 7:08	TL-39-FD	<0.500	Breakroom by library
Crockett ES	6/4/2026 6:35	WC-05-FD	<0.500	outside Room 202; outside Room 202, left cooler
Crockett ES	6/4/2026 6:47	WC-06-FD	<0.500	Across from main gym. Left fountain. Tall.
Crockett ES	6/4/2026 6:56	WC-20-FD	<0.500	Across from 409. Left fountain. No bottle fill.
Crockett ES	6/4/2026 6:56	WC-21-FD	<0.500	Bubbler on right side of the room, Bubbler on the left; 40s hallway, right side of room, left WC
Crockett ES	6/4/2026 6:47	WC-22-FD	<0.500	Bubbler on left side of the room, Bubbler on the right; 40s hallway, left side of room, right WC
Crockett ES	6/4/2026 6:45	WC-25-FD	<0.500	Left wc in front of rm 140
Crockett ES	6/4/2026 6:40	WC-26-FD	<0.500	Boys locker room
Crockett ES	6/4/2026 6:07	WC-27-FD	<0.500	Across from room 505. Next to girls restroom
Crockett ES	6/4/2026 6:05	WC-38-FD	<0.500	100 block girls bathroom
Crockett ES	6/4/2026 6:33	WC-42-FD	0.675	Across from room 338. Left fountain. Next to elevator.
Edmondson ES	6/16/2026 9:26	FB-01	<0.500	Quality Control Field Blank
Edmondson ES	6/16/2026 9:35	WC-39-FD	<0.500	WC on left with bottle filler by boys bathroom and gym entrance
Edmondson ES	6/16/2026 9:36	WC-40-FD	<0.500	Right fountain in hallway with bottle filler by girls bathroom and gym entrance
Edmondson ES	6/16/2026 9:39	SOW-38-FD	<0.500	Room 407
Edmondson ES	6/16/2026 9:41	SOW-37-FD	0.610	Room 404
Edmondson ES	6/16/2026 9:44	WC-45-FD	<0.500	Left fountain in hallway across from restrooms with bottle filler
Edmondson ES	6/16/2026 9:45	WC-46-FD	<0.500	Right fountain in hallway across from restrooms with bottle filler
Edmondson ES	6/16/2026 9:47	SOW-42-FD	<0.500	Room 509
Edmondson ES	6/16/2026 9:49	SOW-06-FD	<0.500	Room 513
Edmondson ES	6/16/2026 9:50	SOW-41-FD	<0.500	Room 504
Edmondson ES	6/16/2026 9:53	SOW-36-FD	<0.500	Room 402
Edmondson ES	6/16/2026 9:56	WC-24-FD	<0.500	Right fountain in hallway by 302 with bottle filler
Edmondson ES	6/16/2026 9:57	SOW-27-FD	<0.500	Room 304
Edmondson ES	6/16/2026 9:59	SOW-28-FD	<0.500	Room 305
Edmondson ES	6/16/2026 10:01	SOW-29-FD	<0.500	Room 309
Edmondson ES	6/16/2026 10:02	SOW-05-FD	<0.500	Room 310
Edmondson ES	6/16/2026 10:05	WC-30-FD	<0.500	Right fountain in hallway by 200 with bottle filler
Edmondson ES	6/16/2026 10:07	WC-31-FD	<0.500	Left fountain in hallway by 200 with bottle filler
Edmondson ES	6/16/2026 10:08	SOW-32-FD	<0.500	Room 201
Edmondson ES	6/16/2026 10:10	SOW-33-FD	<0.500	Room 205
Edmondson ES	6/16/2026 10:13	WC-21-FD	<0.500	Left fountain in hallway by cafeteria entry with bottle filler
Edmondson ES	6/16/2026 10:14	WC-22-FD	<0.500	Right fountain in hallway by cafeteria entry with bottle filler
Edmondson ES	6/16/2026 10:16	KT-03-FD	<0.500	Kitchen prep sink tap
Edmondson ES	6/16/2026 10:16	KT-03-FD-D	<0.500	Kitchen prep sink tap
Fairview ES	6/11/2026 8:53	FB-01	<0.500	Quality Control Field Blank
Fairview ES	6/11/2026 8:57	WC-32-FD	<0.500	WC adj to office and between storage closet, w bottle filler
Fairview ES	6/11/2026 9:02	SOW-34-FD	<0.500	Room 205
Fairview ES	6/11/2026 9:05	SOW-35-FD	<0.500	Room 206
Fairview ES	6/11/2026 9:07	SOW-37-FD	<0.500	Room 204

WILLIAMSON COUNTY SCHOOLS 2026 DRINKING WATER RESULTS SUMMARY				
School Name	Sampled Date/Time	Sample ID	Result	Location Notes
Fairview ES	6/11/2026 9:10	SOW-36-FD	<0.500	Room 203
Fairview ES	6/11/2026 9:13	SOW-41-FD	<0.500	Room 202
Fairview ES	6/11/2026 9:15	SOW-40-FD	<0.500	Room 201
Fairview ES	6/11/2026 9:18	SOW-39-FD	<0.500	Room 104
Fairview ES	6/11/2026 9:18	SOW-39-FD-D	<0.500	Room 104
Fairview ES	6/11/2026 9:21	SOW-38-FD	<0.500	Room 103
Fairview ES	6/11/2026 9:23	SOW-42-FD	<0.500	Room 102
Fairview ES	6/11/2026 9:26	SOW-04-FD	<0.500	Room 101
Fairview ES	6/11/2026 9:32	KT-30-FD	1.12	Kitchen right sink (back wall), right tap, double bay sink
Fairview ES	6/11/2026 9:35	WC-21-FD	<0.500	Adj Room 306, right WC w bottle filler
Fairview ES	6/11/2026 9:36	WC-22-FD	<0.500	Adj Room 306, left WC no bottle filler
Fairview ES	6/11/2026 9:40	WC-43-FD	<0.500	Across from library WC w bottle filler
Fairview ES	6/11/2026 9:45	WC-45-FD	<0.500	Adj Room 501 w bottle filler
Fairview ES	6/11/2026 9:47	WC-23-FD	<0.500	Across from room 506/adj to library, no bottle filler
Fairview ES	6/11/2026 9:50	NS-47-FD	1.05	Nurses sink in rm 128 by 600s hallway
Fairview ES	6/11/2026 9:52	WC-46-FD	<0.500	Adj dual restroom between clinic (fmr 128) and room 406, bottle filler
Fairview ES	6/11/2026 9:55	WC-26-FD	<0.500	Adj Room 602, WC w bottle filler
Fairview ES	6/11/2026 10:00	TL-33-FD	<0.500	Staff lounge
Fairview HS	6/11/2026 6:06	FB-01	<0.500	Quality Control Field Blank
Fairview HS	6/11/2026 6:07	WC-27-FD	<0.500	Across from room C104. Next to boys restroom. bottle filler
Fairview HS	6/11/2026 6:08	WC-28-FD	<0.500	Across from room C104. Next to girls restroom. no bottle filler
Fairview HS	6/11/2026 6:16	WC-43-FD	1.57	Cafeteria water cooler
Fairview HS	6/11/2026 6:20	KT-05-FD	<0.500	2-bay sink on back wall, adj to C119
Fairview HS	6/11/2026 6:20	KT-05-FD-D	<0.500	2-bay sink on back wall, adj to C119
Fairview HS	6/11/2026 6:26	WC-42-FD	<0.500	Left water cooler w bottle filler next to boys restroom across from room F142
Fairview HS	6/11/2026 6:29	WC-02-FD	<0.500	Right water cooler no bottle filler next to girls restroom across from room F142
Fairview HS	6/11/2026 6:34	WC-37-FD	<0.500	G hallway across from G128, right cooler w bottle filler
Fairview HS	6/11/2026 6:35	WC-38-FD	<0.500	G hallway across from G128, left cooler no bottle filler
Fairview HS	6/11/2026 6:39	WC-35-FD	<0.500	By Room G123, right WC w bottle filler adj boys restroom
Fairview HS	6/11/2026 6:41	WC-36-FD	<0.500	By Room G123, left WC no bottle filler adj girls restroom
Fairview HS	6/11/2026 6:44	TL-34-FD	<0.500	Sink in special needs classroom G109
Fairview HS	6/11/2026 6:51	WC-33-FD	<0.500	WC across from room F117, adj boys restroom, left WC w bottle filler
Fairview HS	6/11/2026 6:56	TL-31-FD	1.08	Teacher's lounge sink, room E111
Fairview HS	6/11/2026 6:59	NS-51-FD	0.823	Nurses clinic, admin area
Fairview HS	6/11/2026 7:01	WC-48-FD	<0.500	Adj Gym/C104 and boys restroom, left wc w bottle filler
Fairview HS	6/11/2026 7:06	WC-50-FD	<0.500	Auditorium, adj Room D115
Fairview HS	6/11/2026 7:10	WC-24-FD	4.64	Outside of gym adj Room C104 and girls restroom, right WC no bottle filler
Fairview HS	6/11/2026 7:11	WC-25-FD	0.590	Outside of gym adj Room C104 and boys restroom, left WC w bottle filler
Fairview HS	6/11/2026 7:15	WC-21-FD	1.81	Across from room B111, adj boys restroom, right WC no bottle filler
Fairview HS	6/11/2026 7:16	WC-22-FD	<0.500	across from room B111, adj boys restroom, left WC w bottle filler
Fairview HS	6/11/2026 7:20	TL-45-FD	<0.500	In room between rm b111 and b117. Being used as daycare as of 05/03/22. Sink used for water for kids/babies
Fairview HS	6/11/2026 7:25	WC-46-FD	<0.500	New Auditorium adj women's restroom right, lower unit no bottle filler
Fairview HS	6/11/2026 7:26	WC-47-FD	<0.500	New Auditorium adj men's restroom left, upper unit no bottle filler
Fairview MS	6/11/2026 7:36	FB-01	<0.500	Quality Control Field Blank
Fairview MS	6/11/2026 7:43	WC-31-FD	<0.500	WC in front of Room A117, right WC no bottle filler
Fairview MS	6/11/2026 7:44	WC-32-FD	0.599	WC in front of Room A117, left WC w bottle filler
Fairview MS	6/11/2026 7:48	WC-40-FD	<0.500	Auditorium hallway adj boys restroom, lower right wc no bottle filler
Fairview MS	6/11/2026 7:49	WC-41-FD	<0.500	Left tall wc on right side of auditorium, adj boys restroom no bottle filler
Fairview MS	6/11/2026 7:52	WC-42-FD	<0.500	Auditorium hallway adj girls restroom, lower right wc no bottle filler
Fairview MS	6/11/2026 7:54	WC-43-FD	<0.500	Auditorium hallway adj girls restroom, upper left wc no bottle filler
Fairview MS	6/11/2026 7:57	WC-33-FD	<0.500	Across from counselor office A104, right WC no bottle filler adj boys restroom
Fairview MS	6/11/2026 7:59	WC-34-FD	<0.500	Across from counselor office A104, left WC w bottle filler adj girls restroom
Fairview MS	6/11/2026 8:03	WC-29-FD	<0.500	Across from room B106. Short. w bottle fill. left unit
Fairview MS	6/11/2026 8:05	WC-28-FD	<0.500	Across from room B106. Rall. no bottle fill. right unit
Fairview MS	6/11/2026 8:09	NS-48-FD	<0.500	Rm in front of rm b105
Fairview MS	6/11/2026 8:09	NS-48-FD-D	<0.500	Rm in front of rm b105
Fairview MS	6/11/2026 8:14	WC-22-FD	<0.500	Across from room B115, left upper unit w bottle filler furthest from boys restroom
Fairview MS	6/11/2026 8:15	WC-21-FD	<0.500	Across from room B115, right lower unit no bottle filler closest to boys restroom
Fairview MS	6/11/2026 8:19	WC-23-FD	<0.500	Adj Room D102, across from electrical room, right unit no bottle filler
Fairview MS	6/11/2026 8:23	TL-54-FD	<0.500	Room d101
Fairview MS	6/11/2026 8:26	WC-26-FD	<0.500	Across from room C106, left WC, no bottle filler
Fairview MS	6/11/2026 8:27	WC-25-FD	<0.500	Across from room C106, right WC, w bottle filler
Fairview MS	6/11/2026 8:32	KT-05-FD	0.774	2-bay sink on leftside of kitchen
Fairview MS	6/11/2026 8:37	WC-35-FD	<0.500	Cafeteria WC w bottle filler
Fairview MS	6/11/2026 8:42	WC-37-FD	<0.500	Adj gym, left WC, w bottle filler
Franklin HS	6/18/2026 8:52	FB-01	<0.500	Quality Control Field Blank
Franklin HS	6/18/2026 9:00	KT-17-FD	<0.500	Food prep sink; adjacent to storage closet; right sink
Franklin HS	6/18/2026 9:00	KT-17-FD-D	<0.500	Food prep sink; adjacent to storage closet; right sink
Franklin HS	6/18/2026 9:00	WC-29-FD	<0.500	Right Cafeteria fountain
Franklin HS	6/18/2026 9:06	WC-30-FD	<0.500	Left cafeteria fountain
Franklin HS	6/18/2026 9:09	WC-18-FD	<0.500	Right WC in front of room 203 with bottle filler
Franklin HS	6/18/2026 9:10	WC-03-FD	<0.500	Left WC in front of room 203
Franklin HS	6/18/2026 9:14	WC-19-FD	<0.500	Left WC in front of rm 409

WILLIAMSON COUNTY SCHOOLS 2026 DRINKING WATER RESULTS SUMMARY				
School Name	Sampled Date/Time	Sample ID	Result	Location Notes
Franklin HS	6/18/2026 9:15	WC-20-FD	<0.500	Right wc in front of rm 409 with bottle filler
Franklin HS	6/18/2026 9:19	TL-23-FD	2.13	Teacher's lounge in band room
Franklin HS	6/18/2026 9:31	WC-02-FD	<0.500	Left fountain in hallway in front of 102
Franklin HS	6/18/2026 9:33	WC-15-FD	<0.500	Right fountain in front of room 102 with bottle filler
Franklin HS	6/18/2026 9:36	TL-16-FD	<0.500	Room 100 work room sink
Franklin HS	6/18/2026 9:38	WC-13-FD	<0.500	Right taller cooler by room 009 in office area with bottle filler
Franklin HS	6/18/2026 9:41	WC-14-FD	<0.500	Left shorter cooler by room 009 in office area
Franklin HS	6/18/2026 9:44	WC-11-FD	<0.500	Right fountain adjacent to gym entry with bottle filler
Franklin HS	6/18/2026 9:46	WC-12-FD	<0.500	Left fountain adjacent to gym entry
Franklin HS	6/18/2026 9:47	WC-06-FD	<0.500	Left taller fountain by boys restroom and gym entry
Franklin HS	6/18/2026 9:48	WC-07-FD	<0.500	Right shorter fountain by boys restroom and gym entry
Franklin HS	6/18/2026 9:50	WC-08-FD	<0.500	Left taller fountain by gym entry and main exit
Franklin HS	6/18/2026 9:53	WC-10-FD	<0.500	Men's locker room
Franklin HS	6/18/2026 10:02	TL-24-FD	<0.500	Room 901. 2nd floor.
Franklin HS	6/18/2026 10:05	WC-25-FD	<0.500	Right taller fountain in hallway across from room 907 with bottle filler
Franklin HS	6/18/2026 10:06	WC-04-FD	<0.500	Left shorter fountain in hallway across from room 907
Franklin HS Annex	6/18/2026 10:15	FB-01	<0.500	Quality Control Field Blank
Franklin HS Annex	6/18/2026 10:21	WC-23-FD	<0.500	Hallway beside girls restroom with bottle filler
Franklin HS Annex	6/18/2026 10:22	WC-21-FD	<0.500	Left taller fountain in hallway by boys restroom
Franklin HS Annex	6/18/2026 10:23	WC-22-FD	0.576	Right shorter fountain in hallway by boys restroom
Franklin HS Annex	6/18/2026 10:26	TL-24-FD	<0.500	Teachers work room sink
Franklin HS Annex	6/18/2026 10:26	TL-24-FD-D	<0.500	Teachers work room sink
Franklin HS Annex	6/18/2026 10:30	WC-25-FD	<0.500	Left shorter fountain in hallway by boys bathroom
Franklin HS Annex	6/18/2026 10:31	WC-26-FD	<0.500	Right taller fountain in hallway by boys bathroom
Franklin HS Annex	6/18/2026 10:33	KT-27-FD	<0.500	Cafe sink
Franklin HS Annex	6/18/2026 10:34	WC-28-FD	<0.500	Left taller fountain with bottle filler by elevator
Franklin HS Annex	6/18/2026 10:35	WC-29-FD	<0.500	Right shorter fountain by elevator
Grassland ES	6/9/2026 6:36	SOW-05-FD	<0.500	Room 205
Grassland ES	6/9/2026 6:36	FB-01	<0.500	Quality Control Field Blank
Grassland ES	6/9/2026 6:41	SOW-06-FD	3.18	Room 203
Grassland ES	6/9/2026 6:42	WC-03-FD	<0.500	Hallway by library - lower left fountain
Grassland ES	6/9/2026 6:43	WC-04-FD	<0.500	Hallway by library - upper right fountain with bottle filler
Grassland ES	6/9/2026 6:46	SOW-07-FD	<0.500	Room 200
Grassland ES	6/9/2026 6:48	SOW-08-FD	<0.500	Room 206
Grassland ES	6/9/2026 6:49	SOW-13-FD	<0.500	Room 503
Grassland ES	6/9/2026 6:56	WC-11-FD	<0.500	Right (taller) bottle filler; by room 505
Grassland ES	6/9/2026 6:57	WC-12-FD	<0.500	Left (shorter) cooler; adjacent to room 503
Grassland ES	6/9/2026 7:00	WC-09-FD	<0.500	Left fountain by women's restroom with bottle filler
Grassland ES	6/9/2026 7:01	WC-10-FD	<0.500	Right fountain by boys restroom
Grassland ES	6/9/2026 7:06	SOW-19-FD	<0.500	Room 410
Grassland ES	6/9/2026 7:07	SOW-18-FD	<0.500	Room 408
Grassland ES	6/9/2026 7:09	SOW-17-FD	<0.500	Room 406
Grassland ES	6/9/2026 7:10	WC-22-FD	<0.500	Hallway fountain by storage & electrical room with bottle filler
Grassland ES	6/9/2026 7:15	WC-20-FD	<0.500	Hallway left taller fountain with bottle filler
Grassland ES	6/9/2026 7:16	WC-21-FD	<0.500	Hallway lower right fountain
Grassland ES	6/9/2026 7:17	SOW-22-FD	<0.500	Room 302
Grassland ES	6/9/2026 7:22	TL-02-FD	<0.500	Nurses clinic
Grassland ES	6/9/2026 7:23	KT-23-FD	0.646	Food prep adjacent to to office - used by staff
Grassland ES	6/9/2026 7:23	KT-23-FD-D	0.639	Food prep adjacent to to office - used by staff
Grassland MS	6/9/2026 6:13	KT-12-FD-D	<0.500	Farthest from cafeteria; left sink
Grassland MS	6/9/2026 6:13	KT-12-FD	<0.500	Farthest from cafeteria; left sink
Grassland MS	6/9/2026 6:20	WC-27-FD	<0.500	WC in front of Room A1, (taller) left WC
Grassland MS	6/9/2026 6:22	WC-28-FD	<0.500	WC in front of Room A1, (shorter) right WC
Grassland MS	6/9/2026 6:25	WC-06-FD	<0.500	WC in front of Room A7, left (taller) WC
Grassland MS	6/9/2026 6:26	WC-07-FD	<0.500	Entry to performing arts center by women's restroom - right fountain
Hillsboro ES - MS	6/9/2026 6:15	FB-01	<0.500	Quality Control Field Blank
Hillsboro ES - MS	6/9/2026 6:36	SOW-23-FD	<0.500	Room 302, to the left, bubbler leaks
Hillsboro ES - MS	6/9/2026 6:41	SOW-24-FD	<0.500	Room 301, to the right
Hillsboro ES - MS	6/9/2026 6:41	SOW-24-FD-D	<0.500	Room 301, to the right
Hillsboro ES - MS	6/9/2026 6:44	SOW-03-FD	0.709	115
Hillsboro ES - MS	6/9/2026 6:46	SOW-26-FD	<0.500	Room 303, to the left
Hillsboro ES - MS	6/9/2026 6:48	WC-44-FD	<0.500	Left w bottle filler
Hillsboro ES - MS	6/9/2026 6:54	WC-45-FD	<0.500	Right
Hillsboro ES - MS	6/9/2026 6:57	WC-32-FD	<0.500	Bottle filler
Hillsboro ES - MS	6/9/2026 7:01	SOW-46-FD	0.774	Room 110
Hillsboro ES - MS	6/9/2026 7:03	SOW-47-FD	0.886	Room 303
Hillsboro ES - MS	6/9/2026 7:07	WC-48-FD	<0.500	Cafeteria
Hillsboro ES - MS	6/9/2026 7:09	WC-39-FD	<0.500	WC on right with bottle filler
Hillsboro ES - MS	6/9/2026 7:10	WC-40-FD	<0.500	Left
Hillsboro ES - MS	6/9/2026 7:13	WC-04-FD	<0.500	Right WC in hallway near music room

WILLIAMSON COUNTY SCHOOLS 2026 DRINKING WATER RESULTS SUMMARY				
School Name	Sampled Date/Time	Sample ID	Result	Location Notes
Hillsboro ES - MS	6/9/2026 7:17	WC-49-FD	<0.500	Theater: taller by men's bathroom
Hillsboro ES - MS	6/9/2026 7:19	WC-50-FD	<0.500	Theater: nearest women's rr (taller)
Hillsboro ES - MS	6/9/2026 7:21	WC-52-FD	<0.500	Theater. Next to the girls' restroom. Left fountain.
Hillsboro ES - MS	6/9/2026 7:24	WC-51-FD	<0.500	Theater building. Next to the boys' restroom. Right fountain.
Hillsboro ES - MS	6/9/2026 7:29	KT-05-FD	<0.500	3-bay kitchen sink furthest right, closest to door
Hunters Bend ES	6/2/2026 6:05	FB-01	<0.500	Quality Control Field Blank
Hunters Bend ES	6/2/2026 6:15	WC-21-FD	<0.500	Between Room 202 & boys bathroom, left WC & sampled from bottle filler
Hunters Bend ES	6/2/2026 6:15	WC-21-FD-D	<0.500	Between Room 202 & boys bathroom, left WC & sampled from bottle filler
Hunters Bend ES	6/2/2026 6:16	WC-22-FD	<0.500	Between Room 202 & Boys bathroom, right WC
Hunters Bend ES	6/2/2026 6:17	TL-52-FD	<0.500	Adj 117
Hunters Bend ES	6/2/2026 6:19	WC-24-FD	<0.500	WC next to C4 & C5 rooms, right (shorter) WC
Hunters Bend ES	6/2/2026 6:20	WC-25-FD	<0.500	WC next to room C2, in front of library, left (taller) WC, sampled from bottle filler
Hunters Bend ES	6/2/2026 6:21	SOW-51-FD	<0.500	Room 410
Hunters Bend ES	6/2/2026 6:23	SOW-49-FD	4.20	Room 404
Hunters Bend ES	6/2/2026 6:30	SOW-26-FD	5.73	Room 303, to the left
Hunters Bend ES	6/2/2026 6:33	SOW-23-FD	4.85	Room 302, to the left, bubbler leaks
Hunters Bend ES	6/2/2026 6:37	SOW-32-FD	<0.500	Room 306
Hunters Bend ES	6/2/2026 6:41	SOW-31-FD	2.42	Room 303
Hunters Bend ES	6/2/2026 6:43	SOW-30-FW	4.20	Room across from gym at the end of hallway
Hunters Bend ES	6/2/2026 6:46	WC-28-FD	<0.500	WC in front of Room A1, (shorter) right WC
Hunters Bend ES	6/2/2026 6:47	WC-29-FD	<0.500	WC in front of Room A4, taller, left WC. Sampled from bubbler head, bottle filler not working
Hunters Bend ES	6/2/2026 6:50	SOW-45-FD	<0.500	Room 114
Hunters Bend ES	6/2/2026 6:52	SOW-46-FD	<0.500	Room 110
Hunters Bend ES	6/2/2026 6:53	WC-35-FD	<0.500	WC in front of Room A19, right (shorter) WC
Hunters Bend ES	6/2/2026 6:54	WC-34-FD	<0.500	Left WC, next to Room 201 & boy's restroom
Hunters Bend ES	6/2/2026 7:03	KT-42-FD	0.507	Adjacent to kitchen office
Hunters Bend ES	6/2/2026 7:06	WC-41-FD	<0.500	WC in front of Room 620, left WC
Hunters Bend ES	6/2/2026 7:07	WC-40-FD	<0.500	WC in cafeteria
Hunters Bend ES	6/2/2026 7:08	SOW-43-FD	<0.500	Room 209
Hunters Bend ES	6/2/2026 7:10	SOW-38-FD	<0.500	Room 703, art room, bubbler has paint on it, dirty sink
Hunters Bend ES	6/2/2026 7:26	SOW-50-FD	10.8	Room 409
Hunters Bend ES	6/2/2026 7:32	SOW-33-FD	<0.500	Room 305
Hunters Bend ES	6/2/2026 7:35	SOW-47-FD	<0.500	Room 303
Hunters Bend ES	6/2/2026 7:36	SOW-48-FD	<0.500	Room 300
Hunters Bend ES	6/2/2026 7:39	SOW-37-FD	0.938	Room 701, music room. To the right
Hunters Bend ES	6/2/2026 7:40	SOW-36-FD	<0.500	Room 310
Hunters Bend ES	6/2/2026 7:45	SOW-42-FD	<0.500	Room 206
Hunters Bend ES	6/2/2026 7:47	SOW-44-FD	<0.500	Room 212
Hunters Bend ES	6/2/2026 7:48	SOW-39-FD	<0.500	Room 104
Lipscomb ES	6/16/2026 8:00	FB-01	<0.500	Quality Control Field Blank
Lipscomb ES	6/16/2026 8:03	KT-02-FD	<0.500	Kitchen tap nearest to office (no prep sink sticker)
Lipscomb ES	6/16/2026 8:03	KT-02-FD-D	<0.500	3 bay sink by exit doors, left faucet
Lipscomb ES	6/16/2026 8:12	WC-21-FD	<0.500	Upper left fountain in hallway by room 302 with bottle filler
Lipscomb ES	6/16/2026 8:14	WC-22-FD	<0.500	Lower right fountain in hallway by room 302
Lipscomb ES	6/16/2026 8:16	SOW-23-FD	<0.500	Room 305
Lipscomb ES	6/16/2026 8:17	SOW-46-FD	<0.500	Room 306
Lipscomb ES	6/16/2026 8:18	SOW-24-FD	<0.500	Room 309
Lipscomb ES	6/16/2026 8:21	SOW-47-FD	<0.500	Room 312
Lipscomb ES	6/16/2026 8:23	SOW-48-FD	<0.500	Room 311
Lipscomb ES	6/16/2026 8:24	SOW-25-FD	<0.500	Room 313
Lipscomb ES	6/16/2026 8:26	SOW-42-FD	<0.500	Room 317
Lipscomb ES	6/16/2026 8:29	SOW-26-FD	<0.500	Room 318
Lipscomb ES	6/16/2026 8:33	SOW-43-FD	<0.500	Room 402
Lipscomb ES	6/16/2026 8:36	WC-35-FD	<0.500	Left water fountain in hallway by boys restroom with bottle filler
Lipscomb ES	6/16/2026 8:37	WC-36-FD	<0.500	Right water fountain in hallway by girls restroom
Lipscomb ES	6/16/2026 8:42	SOW-06-FD	<0.500	Room 410
Lipscomb ES	6/16/2026 8:44	SOW-37-FD	<0.500	411
Lipscomb ES	6/16/2026 8:47	WC-30-FD	<0.500	Fountain in hallway by 501 with bottle filler
Lipscomb ES	6/16/2026 8:50	SOW-45-FD	<0.500	Room 204
Lipscomb ES	6/16/2026 8:52	SOW-04-FD	<0.500	Room 205
Lipscomb ES	6/16/2026 8:55	SOW-41-FD	<0.500	Room 202
Lipscomb ES	6/16/2026 8:56	SOW-40-FD	<0.500	Room 203
Lipscomb ES	6/16/2026 8:59	SOW-39-FD	<0.500	Room 200
Lipscomb ES	6/16/2026 9:02	WC-37-FD	<0.500	Lower left fountain in hallway by room 200 with bottle filler
Lipscomb ES	6/16/2026 9:03	WC-38-FD	<0.500	Taller right fountain in hallway by room 200
Oak View ES	6/11/2026 6:04	FB-01	<0.500	Quality Control Field Blank
Oak View ES	6/11/2026 6:05	TL-40-FD	<0.500	Teacher's lounge sink
Oak View ES	6/11/2026 6:05	WC-07-FD	<0.500	WC on the right, across hall from Room 402
Oak View ES	6/11/2026 6:08	WC-58-FD	<0.500	Left WC with bottle filler, in front of rm 402
Oak View ES	6/11/2026 6:10	SOW-24-FD	<0.500	Room 404
Oak View ES	6/11/2026 6:13	SOW-09-FD	0.561	Room 405

WILLIAMSON COUNTY SCHOOLS 2026 DRINKING WATER RESULTS SUMMARY				
School Name	Sampled Date/Time	Sample ID	Result	Location Notes
Oak View ES	6/11/2026 6:20	SOW-42-FD	<0.500	Room 406, back right corner
Oak View ES	6/11/2026 6:24	SOW-26-FD	<0.500	Room 410
Oak View ES	6/11/2026 6:26	SOW-03-FD	<0.500	Room 409
Oak View ES	6/11/2026 6:28	SOW-08-FD	<0.500	Room 408
Oak View ES	6/11/2026 6:30	SOW-25-FD	<0.500	Room 407
Oak View ES	6/11/2026 6:32	SOW-23-FD	1.22	Room 402
Oak View ES	6/11/2026 6:34	SOW-14-FD	<0.500	Room 205
Oak View ES	6/11/2026 6:36	SOW-18-FD	<0.500	Room 506
Oak View ES	6/11/2026 6:38	SOW-19-FD	<0.500	Room 507
Oak View ES	6/11/2026 6:40	SOW-21-FD	<0.500	Room 511
Oak View ES	6/11/2026 6:42	SOW-04-FD	<0.500	Room 513, to the left
Oak View ES	6/11/2026 6:44	SOW-15-FD	<0.500	Room 501
Oak View ES	6/11/2026 6:46	SOW-17-FD	<0.500	Room 211
Oak View ES	6/11/2026 6:48	SOW-05-FD	<0.500	Room 212
Oak View ES	6/11/2026 6:50	WC-16-FD	<0.500	Sink on the right, across hall from the Gym
Oak View ES	6/11/2026 6:51	WC-50-FD	<0.500	Next to WC-16, between bathrooms, in front of gym doors. Left WC, sample from regular bubble head.
Oak View ES	6/11/2026 6:53	SOW-22-FD	1.31	Room 209
Oak View ES	6/11/2026 6:55	SOW-13-FD	<0.500	Room 204
Oak View ES	6/11/2026 6:58	SOW-11-FD	<0.500	Room 304
Oak View ES	6/11/2026 6:58	WC-10-FD	<0.500	WC on the right, across hall from Room 301
Oak View ES	6/11/2026 6:58	WC-45-FD	<0.500	cooler on left with bottle filter, sampling from bottle filter
Oak View ES	6/11/2026 7:00	SOW-12-FD	<0.500	Room 307
Oak View ES	6/11/2026 7:07	KT-02-FD	<0.500	Kitchen; Adjacent to the office and fire extinguisher
Oak View ES	6/11/2026 7:07	KT-02-FD-D	<0.500	Kitchen; Adjacent to the office and fire extinguisher
Oak View ES	6/11/2026 7:10	KT-06-FD	<0.500	Sink on the right, in the corner
Page HS	6/2/2026 9:45	FB-01	<0.500	Quality Control Field Blank
Page HS	6/2/2026 9:49	WC-20-FD	<0.500	Right fountain next to mechanical room/concessions stand
Page HS	6/2/2026 9:52	WC-21-FD	<0.500	Left middle WC by concessions stand
Page HS	6/2/2026 9:55	WC-23-FD	<0.500	WC by boys locker room with bottle filler
Page HS	6/2/2026 9:57	WC-22-FD	3.82	Fountain by girls locker room
Page MS	6/2/2026 8:51	FB-01	<0.500	Quality Control Field Blank
Page MS	6/2/2026 8:53	WC-36-FD	1.21	Next to Room 613 (office room)
Page MS	6/2/2026 8:56	WC-35-FD	1.18	WC in front of Room A19, right (shorter) WC
Page MS	6/2/2026 8:56	WC-39-FD	<0.500	WC on left, no bottle filler
Page MS	6/2/2026 9:02	WC-20-FD	<0.500	Lower left fountain next to women's bathroom
Page MS	6/2/2026 9:03	WC-21-FD	<0.500	Hallway by boys bathroom, right fountain with bottle filler
Page MS	6/2/2026 9:07	WC-24-FD	<0.500	Left fountain in cafeteria, right of entry from hallway by microwaves
Page MS	6/2/2026 9:09	WC-25-FD	<0.500	Right fountain in cafeteria with bottle filler, right of entry from hallway next to microwaves
Page MS	6/2/2026 9:11	KT-33-FD	<0.500	Kitchen dish, left tap
Page MS	6/2/2026 9:13	KT-34-FD	<0.500	Kitchen dish, right tap
Page MS	6/2/2026 9:13	KT-34-FD-D	0.727	Kitchen dish, right tap
Page MS	6/2/2026 9:18	WC-38-FD	<0.500	In cafeteria, did not sample from bottle filler
Page MS	6/2/2026 9:23	WC-27-FD	<0.500	In hall by women's restroom, (taller) left WC
Page MS	6/2/2026 9:24	WC-28-FD	<0.500	In hall by men's restroom (shorter) right WC with bottle filler
Page MS	6/2/2026 9:27	WC-29-FD	1.01	Left WC in front of Room C6
Page MS	6/2/2026 9:28	WC-30-FD	1.20	Right WC in front of Room C6
Page MS	6/2/2026 9:31	WC-31-FD	<0.500	Left WC across from C14
Page MS	6/2/2026 9:32	WC-32-FD	<0.500	Right WC across from C14
Pinewood ES	6/9/2026 7:50	FB-01	<0.500	Quality Control Field Blank
Pinewood ES	6/9/2026 7:58	WC-04-FD	<0.500	Across from Room 702A, bubbler without bottle filler (bubbler on the right)
Pinewood ES	6/9/2026 7:58	WC-04-FD-D	<0.500	Across from Room 702A, bubbler without bottle filler (bubbler on the right)
Renaissance HS	6/11/2026 7:25	FB-01	<0.500	Quality Control Field Blank
Renaissance HS	6/11/2026 7:26	WC-01-FD	<0.500	Across from kitchen.
Renaissance HS	6/11/2026 7:26	WC-06-FD	<0.500	Across from main gym. Left fountain. Tall.
Renaissance HS	6/11/2026 7:30	WC-02-FD	<0.500	Across the hallway from women's restroom, adjacent to exterior exit, left cooler. Basement floor
Renaissance HS	6/11/2026 7:30	WC-05-FD	<0.500	Right WC. Basement floor
Renaissance HS	6/11/2026 7:35	WC-04-FD	<0.500	Adjacent to Room 204 and stairwell door, left cooler. 2nd floor
Renaissance HS	6/11/2026 7:35	WC-04-FD-D	<0.500	Adjacent to Room 204 and stairwell door, left cooler. 2nd floor
Renaissance HS	6/11/2026 7:35	WC-07-FD	<0.500	Right WC with filter. 2nd floor; Right WC with filter. Sample taken from filter not regular bubble head. 2nd floor
Scales ES	6/4/2026 8:10	FB-01-FD	<0.500	Quality Control Field Blank
Scales ES	6/4/2026 8:29	WC-49-FD	<0.500	Left WC tall with bottle filler, by school entrance in between bathrooms
Scales ES	6/4/2026 8:29	WC-49-FD-D	<0.500	Left WC tall with bottle filler, by school entrance in between bathrooms
Scales ES	6/4/2026 8:30	WC-24-FD	<0.500	WC next to C4 & C5 rooms, right (shorter) WC
Scales ES	6/4/2026 8:38	WC-41-FD	<0.500	WC in front of Room 620, left WC
Scales ES	6/4/2026 8:39	WC-40-FD	<0.500	WC in cafeteria
Scales ES	6/4/2026 8:41	SOW-25-FD	0.551	Room 304, to the right, leaks water
Scales ES	6/4/2026 8:44	SOW-27-FD	0.766	Room 305, to the right
Scales ES	6/4/2026 8:47	SOW-26-FD	0.713	Room 303, to the left
Scales ES	6/4/2026 8:50	SOW-28-FD	<0.500	Room 306, to the left, leaks some water

WILLIAMSON COUNTY SCHOOLS 2026 DRINKING WATER RESULTS SUMMARY				
School Name	Sampled Date/Time	Sample ID	Result	Location Notes
Scales ES	6/4/2026 8:53	SOW-29-FD	1.05	Room 307, to the left
Scales ES	6/4/2026 8:55	SOW-31-FD	<0.500	Room 303
Scales ES	6/4/2026 8:57	SOW-30-FD	1.37	Room 308, to the right
Scales ES	6/4/2026 8:59	SOW-04-FD	1.52	Room 413
Scales ES	6/4/2026 9:05	WC-13-FD	<0.500	Cafeteria
Scales ES	6/4/2026 9:11	WC-14-FD	<0.500	2nd floor, right WC in front of rm 224
Scales ES	6/4/2026 9:14	WC-42-FD	<0.500	WC in front of Room B18
Scales ES	6/4/2026 9:15	WC-15-FD	<0.500	2nd floor, left WC in front of rm 224
Scales ES	6/4/2026 9:20	SOW-44-FD	<0.500	Room 212
Scales ES	6/4/2026 9:23	SOW-16-FD	<0.500	Room 210
Scales ES	6/4/2026 9:27	SOW-33-FD	<0.500	Room 305
Scales ES	6/4/2026 9:30	SOW-19-FD	<0.500	Room 305
Scales ES	6/4/2026 9:33	WC-45-FD	<0.500	Left wc outside of room 506 and 507
Scales ES	6/4/2026 9:34	SOW-17-FD	<0.500	Room 207
Scales ES	6/4/2026 9:36	SOW-07-FD	<0.500	Room 200
Scales ES	6/4/2026 9:40	KT-02-FD	<0.500	3 bay sink by exit doors, left faucet
Scales ES	6/4/2026 9:42	WC-20-FD	<0.500	Next to mechanical room
Scales ES	6/4/2026 9:45	WC-22-FD	<0.500	Between Room 202 & Boys bathroom, right WC
Scales ES	6/4/2026 9:46	WC-47-FD	<0.500	Left WC with bottle filler outside gym
Scales ES	6/4/2026 9:49	WC-46-FD	<0.500	Wc in 500 hallway right WC, HAS BOTTLE FILLER
Scales ES	6/4/2026 9:50	WC-21-FD	<0.500	Between Room 202 & boys bathroom, left WC & sampled from bottle filler
Scales ES	6/4/2026 9:52	WC-52-FD	<0.500	Right WC by gym hallway
Scales ES	6/4/2026 9:53	WC-09-FD	<0.500	Left WC by gym hallway
Scales ES	6/4/2026 9:57	WC-48-FD	<0.500	Right wc outside gym
Scales ES	6/4/2026 9:59	WC-23-FD	<0.500	WC next to C4 & C5 rooms, left (taller) WC
Trinity ES	6/2/2026 7:25	FB-01	<0.500	Quality Control Field Blank
Trinity ES	6/2/2026 7:28	WC-44-FD	<0.500	Right WC in between gym and main office
Trinity ES	6/2/2026 7:29	WC-43-FD	<0.500	Left WC in between gym and main office has bottle filler; Left WC in between gym and main office
Trinity ES	6/2/2026 7:30	WC-45-FD	<0.500	Single WC in front of 100s hallway
Trinity ES	6/2/2026 7:36	SOW-04-FD	<0.500	Room 110
Trinity ES	6/2/2026 7:40	WC-47-FD	<0.500	Single WC in between 100s and 200s hallway, has bottle filler; Single WC in between 100s and 200s hallway
Trinity ES	6/2/2026 7:43	WC-20-FD	<0.500	outside Room 202, yellow hall, right wc with bottle filler; outside Room 202, yellow hall
Trinity ES	6/2/2026 7:44	WC-05-FD	<0.500	Near room 202, left wc; Near room 202
Trinity ES	6/2/2026 7:47	WC-29-FD	<0.500	Outside Room 302, left cooler
Trinity ES	6/2/2026 7:48	WC-30-FD	<0.500	Outside Room 302, right cooler
Trinity ES	6/2/2026 7:49	SOW-06-FD	<0.500	Room 310
Trinity ES	6/2/2026 7:51	SOW-32-FD	<0.500	Room 305
Trinity ES	6/2/2026 7:52	SOW-33-FD	<0.500	Room 307
Trinity ES	6/2/2026 7:53	SOW-31-FD	<0.500	Room 304
Trinity ES	6/2/2026 7:56	WC-34-FD	<0.500	Outside Room 402, left cooler
Trinity ES	6/2/2026 7:57	WC-35-FD	<0.500	Outside Room 402, right cooler
Trinity ES	6/2/2026 7:59	SOW-36-FD	0.594	Room 404
Trinity ES	6/2/2026 8:00	SOW-48-FD	<0.500	Room 405
Trinity ES	6/2/2026 8:03	SOW-38-FD	0.635	Room 410
Trinity ES	6/2/2026 8:04	WC-39-FD	<0.500	Hall outside cafeteria, left cooler
Trinity ES	6/2/2026 8:07	WC-40-FD	<0.500	hall outside cafeteria, right cooler
Trinity ES	6/2/2026 8:11	SOW-23-FD	<0.500	Room 215
Trinity ES	6/2/2026 8:12	SOW-24-FD	<0.500	Room 216
Trinity ES	6/2/2026 8:17	SOW-26-FD	<0.500	Room 102
Trinity ES	6/2/2026 8:28	TL-50-FD	<0.500	Main office teacher's lounge
Trinity ES	6/2/2026 8:30	WC-41-FD	<0.500	In main office
Trinity ES	6/2/2026 8:39	KT-49-FD	<0.500	Kitchen sink to the right, left fixture; Kitchen sink to the right
Trinity ES	6/2/2026 8:39	KT-49-FD-D	<0.500	Kitchen sink to the right
Trinity ES	6/2/2026 8:43	SOW-21-FD	<0.500	Room 213
Trinity ES	6/2/2026 8:46	SOW-22-FD	<0.500	Room 212
Trinity ES	6/2/2026 8:48	SOW-37-FD	<0.500	Room 403
Walnut Grove ES	6/2/2026 8:02	FB-01	<0.500	Quality Control Field Blank
Walnut Grove ES	6/2/2026 8:23	SOW-48-FD	<0.500	Room 300
Walnut Grove ES	6/2/2026 8:10	KT-23-FD	<0.500	Prep sink adjacent to Room 507
Walnut Grove ES	6/2/2026 8:17	WC-04-FD	<0.500	Across from Room 702A, bubbler without bottle filler (bubbler on the right)
Walnut Grove ES	6/2/2026 8:46	SOW-45-FD	<0.500	Room 114
Walnut Grove ES	6/2/2026 9:07	WC-49-FD	<0.500	WC in main office
Walnut Grove ES	6/2/2026 8:38	WC-37-FD	<0.500	WC in front of Room A22, right (shorter) WC
Walnut Grove ES	6/2/2026 8:51	OW-47-FD	<0.500	CR 806
Walnut Grove ES	6/2/2026 9:03	WC-42-FD	<0.500	WC in front of Room B18
Walnut Grove ES	6/2/2026 9:02	WC-43-FD	<0.500	Left WC with bottle filler 700 hallway
Walnut Grove ES	6/2/2026 8:25	SOW-31-FD	<0.500	Room 303
Walnut Grove ES	6/2/2026 8:34	WC-36-FD	<0.500	Next to Room 613 (office room)
Walnut Grove ES	6/2/2026 8:27	WC-27-FD	<0.500	WC in front of Room A1, (taller) left WC
Walnut Grove ES	6/2/2026 8:16	WC-05-FD	<0.500	Left unit w/bottle filler, adj Room 617; left WC in between cafeteria and 700s hallway

WILLIAMSON COUNTY SCHOOLS 2026 DRINKING WATER RESULTS SUMMARY				
School Name	Sampled Date/Time	Sample ID	Result	Location Notes
Walnut Grove ES	6/2/2026 8:20	WC-28-FD	<0.500	WC in front of Room A1, (shorter) right WC
Walnut Grove ES	6/2/2026 8:20	WC-28-FD-D	<0.500	WC in front of Room A1, (shorter) right WC
Walnut Grove ES	6/2/2026 8:48	SOW-39-FD	<0.500	Room 104
Walnut Grove ES	6/2/2026 9:13	SOW-02-FD	<0.500	310
Walnut Grove ES	6/2/2026 8:58	SOW-41-FD	<0.500	Room 205
Walnut Grove ES	6/2/2026 8:41	TL-26-FD	<0.500	Main office, room closest to lobby
Walnut Grove ES	6/2/2026 8:30	WC-33-FD	<0.500	WC in front of Room A14, right (shorter) WC
Walnut Grove ES	6/2/2026 9:15	SOW-30-FD	<0.500	Room 308, to the right
Walnut Grove ES	6/2/2026 8:53	OW-38-FD	<0.500	Room 808
Walnut Grove ES	6/2/2026 8:39	WC-44-FD	<0.500	Left taller wc no bottle filler 100s hallway
Walnut Grove ES	6/2/2026 8:31	WC-34-FD	<0.500	Left WC, next to Room 201 & boy's restroom
Woodland MS	6/4/2026 7:23	FB-01	<0.500	Quality Control Field Blank
Woodland MS	6/4/2026 7:24	WC-30-FD	<0.500	Hallway outside Room 201/203 on right
Woodland MS	6/4/2026 7:26	TL-42-FD	<0.500	Teacher Lounge/Work room
Woodland MS	6/4/2026 7:29	KT-41-FD	<0.500	Classroom. Sink.
Woodland MS	6/4/2026 7:35	WC-32-FD	<0.500	WC in front of Room A14, left (taller) WC
Woodland MS	6/4/2026 7:39	WC-33-FD	<0.500	Office fountain across from room 158
Woodland MS	6/4/2026 7:40	WC-34-FD	<0.500	WC in front of Room A19, left (taller) WC
Woodland MS	6/4/2026 7:43	WC-35-FD	<0.500	By Room G123, right WC
Woodland MS	6/4/2026 7:44	WC-36-FD	<0.500	By Room G123, left WC
Woodland MS	6/4/2026 7:46	WC-37-FD	<0.500	G hallway across from G128, right cooler
Woodland MS	6/4/2026 7:46	WC-06-FD	<0.500	Across from main gym. Left fountain. Tall.
Woodland MS	6/4/2026 7:49	WC-39-FD	<0.500	100 block boys bathroom
Woodland MS	6/4/2026 7:49	KT-03-FD	0.539	Food prep sink
Woodland MS	6/4/2026 7:54	KT-03-FD-D	<0.500	Food prep sink
Woodland MS	6/4/2026 7:54	KT-20-FD	<0.500	Dish washing tap
Woodland MS	6/4/2026 7:56	WC-21-FD	<0.500	Bubbler on right side of the room, Bubbler on the left; 40s hallway, right side of room, left WC
Woodland MS	6/4/2026 8:00	WC-43-FD	<0.500	Across from room 338. Right fountain. No bottle fill. Next to girls restroom.
Woodland MS	6/4/2026 8:02	WC-48-FD	<0.500	Hallway outside gym, right fountain with no bottle filler
Woodland MS	6/4/2026 8:04	WC-23-FD	<0.500	Bubbler on left side of the room, Bubbler on the right; 20s hallway, left side of room, by Room 24, right WC
Woodland MS	6/4/2026 8:08	WC-24-FD	<0.500	Bubbler on right side of the room, Bubbler on the left; 20s hallway, by Room 22, right WC
Woodland MS	6/4/2026 8:08	KT-44-FD	1.48	Concession Stand next to gym.
Woodland MS	6/4/2026 8:10	WC-45-FD	<0.500	Boys locker room, has bottle filler
Woodland MS	6/4/2026 8:13	WC-38-FD	<0.500	100 block girls bathroom
Woodland MS	6/4/2026 8:21	WC-25-FD	<0.500	Left wc in front of rm 140
Woodland MS	6/4/2026 8:23	WC-26-FD	<0.500	Boys locker room
Woodland MS	6/4/2026 8:23	WC-49-FD	<0.500	Left fountain left of auditorium door
Woodland MS	6/4/2026 8:25	WC-50-FD	<0.500	Right fountain left of auditorium door
Woodland MS	6/4/2026 8:31	WC-27-FD	<0.500	Across from room 505. Next to girls restroom
Woodland MS	6/4/2026 8:31	WC-28-FD	<0.500	Across from room 505. Next to boys restroom.
Woodland MS	6/4/2026 8:35	TL-47-FD	<0.500	Teachers lounge near cafeteria and rm 207
Woodland MS	6/4/2026 7:32	WC-31-FD	<0.500	WC in front of Room A7, right (shorter) WC

FIXTURE TYPE	
SOW	Sink with Bubbler
WC	Water Cooler
KT	Kitchen Tap
NS	Nurse's Clinic
TL	Teacher's Lounge
FB	Quality Control Field Blank

Notes:

- Results are in parts per billion (ppb).
- "-FD" sample ID suffix indicates sample is a First Draw sample collected from a fixture.
- "-FD-D" sample ID suffix indicates a duplicate First Draw sample collected from a fixture
- "FB-01" sample is a Field Blank sample of distilled water poured into a container in the field & shipped to laboratory with field samples for quality control purposes.